

--58. The water spa for bathing of claim 54, wherein an error message is displayed on the control panel in alphanumeric characters when lack of water flow is detected by the second sensor.

REMARKS


By this paper, original claims 1-34 have been canceled and new claims 35-58 added.

Claims 35-58 are pending.

In addition, certain amendments were made to the specification for clarification to correct errors. It is believed that no new matter has been added.

Respectfully submitted,

FULWIDER PATTON LEE & UTECHT, LLP



John V. Hanley
Registration No. 38,171

JVH:kst
Howard Hughes Center
6060 Center Drive, Tenth Floor
Los Angeles, CA 90045
Tel. No. (310) 824-5555
Fax No. (310) 824-9696
#192403